

ECS Configuration Change Request

Page 1 of

Page(s)

| | | | | | | |
|---|--------------------------------|----------------------------------|---|---|--|-----------------------|
| 1. Originator Maryellen Corbett | 2. Log Date: 1/22/02 | 3. CCR #: 02-0054 | 4. Rev: - | 5. Tel: 301 925-0703 | 6. Rm #: 2072C | 7. Dept. SE |
| 8. CCR Title: January 2002 Baseline Updates | | | | | | |
| 9. Originator Signature/Date Maryellen Corbett /s/ 1/22/02 | | | 10. Class II | 11. Type: CCR | 12. Need Date: 02/28/2002 | |
| 13. Office Manager Signature/Date Carolyn Whitaker /s/ 1/22/02 | | | 14. Category of Change: Initial ECS Baseline Doc. | | 15. Priority: (If "Emergency" fill in Block 27). Routine | |
| 16. Documentation/Drawings Impacted: 920-TDG-002, 920-TDN-002, 920-TDE-002, 920-TDP-002, 920-TDE-002, 920-TDV-002, 910-TDA-005 | | | 17. Schedule Impact: | | 18. CI(s) Affected: | |
| 19. Release Affected by this Change: 6A | | 20. Date due to Customer: | | 21. Estimated Cost: None - Under 100K | | |
| 22. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input type="checkbox"/> Other: | | | | | | |
| 23. Problem: (use additional Sheets if necessary) Baseline updates have been identified on attached pages.. | | | | | | |
| 24. Proposed Solution: (use additional sheets if necessary) Make baseline updates as identified on attached pages and red-line mark-ups. | | | | | | |
| 25. Alternate Solution: (use additional sheets if necessary) Inconsistent Baseline | | | | | | |
| 26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Inconsistent Baseline | | | | | | |
| 27. Justification for Emergency (If Block 15 is "Emergency"): | | | | | | |
| 28. Site(s) Affected: <input type="checkbox"/> EDF <input checked="" type="checkbox"/> PVC <input checked="" type="checkbox"/> VATC <input type="checkbox"/> EDC <input checked="" type="checkbox"/> GSFC <input type="checkbox"/> LaRC <input checked="" type="checkbox"/> NSIDC <input checked="" type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other | | | | | | |
| 29. Board Comments: | | | | 30. Work Assigned To: | 31. CCR Closed Date: | |
| 32. EDF/SCDV CCB Chair (Sign/Date): A. Abtahi /s/ 1/30/02 | | | Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS | | | |
| 33. M&O CCB Chair (Sign/Date): Gary Gavigan /s/ 2/12/02 | | | Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS | | | |
| 34. ECS CCB Chair (Sign/Date): | | | Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS | | | |

ADDITIONAL SHEET

CCR #: 02-0054 **Rev: - Originator:** Maryellen Corbett

Telephone: 0703 **Office:** SE

Title of Change: January 2002 Baseline Updates

Baseline Updates:

1. Add FLEXlm 6.1 to the software map of GSFC hosts: g0drg01 and g0drg02. Infrastructure documents 920-TDG-003 are correct and On-Line Discrepancy Reports indicate that FLEXlm is correct installed and configured on both these hosts.
2. Update 920-TDN-003 to change the identified SGI FLEXlm server from n0acg01 to n0dig06. Software is installed and configured on n0aag02 and is not installed and configured on n0acg01. Remove FLEXlm from n0acg02 H/W Software baseline.
3. Update 920-TDV-003 to change the identified SGI FLEXlm servers to t1acg04, t1spg03 and t1drg03. Also remove FLEXlm from t1mss04 as this host should not be designated as a Sun FLEXlm license servers.
4. Remove FLEXlm from baseline of n0ais01. FLEXlm is not installed as License Manager and should not be identified on the baseline.
5. Update 920-TDE-003 to change the identified Sun FLEXlm server from e0mss02 to e0css02. Only this baseline document needs update.
6. Update Oracle and Oracle Developer path on COTS version baseline to:
/usr/ecs/OPS/COTS/oracle
7. Change the version of Secure Shell Commercial Client to 2.4.0 to conform with the interrogation process. COTS version baseline update will make change to all appropriate COTS HW/SW map entries.
8. Update Sun patch # 103663-15 in the Sun Common OS Patch Bundle to # 103663-16 for all Sun hosts.
9. Remove FLEXlm from p2sps06. Host is should not be configured as a license server and license server not currently installed.
10. Remove the FLEXlm License Server function from m0mss16 as this host does not currently function as a license server.

System Administrator Updates: (also see ECOs)

1. Remove HPs batgirl and minator and turn over to ILS.